

Project 25-15 - City of North Battleford
Mike Lepp 445-1753
Cell 480-7898

Building Name: Don Ross Center

Building No. 03

N. Battleford, SK

Page 5

Date: June 18, 2025

Sample No.	Location in Building	Sample Type	Sample Descripton	Phase Percent of Total	Asbestos Content ?	Other parts of This Phase
	Basement Washroom (By Room 104)					
DR-36	East Wall	Drywall	Brown Paper	2 + 2	ND	100% Cellulose
			Off-white Cementicious	96	ND	100% NF
DR-37	East Wall	Drywall	Paint	2	ND	100% NF
		Mud	White, Cementicious	98	ND	100% NF
DR-38A	West Wall	Plaster	Grey Paint	2	ND	100% NF
		Joint Compund	Grey, Cementicious	98	ND	100% NF
DR-38B	same	Plaster	Grey, Cementicious	100	ND	100% NF
		Skim Coat				
DR-38C	same	Plaster	Beige, Cementicious	100	ND	<1% Horse Hair, 99% NF
		Base Coat				
	Janitor's Room (in Washroom area)					
DR-39A	South Wall	Plaster	Green Paint	5	ND	100% NF
		Skim Coat	White, Cementicious	96	ND	100% NF
DR-39B	same	Plaster	White/Gold, Cementicious	100	ND	<1% Actinolite, >99% NF
		Base Coat 1				
DR-39C	same	Plaster	Grey, Cementicious	100	ND	100% NF
		Base Coat 2				
DR-40	Floor Tile	Floor Tile	White, Blue Flecks, Vinyl	100	ND	100% NF
		12" x 12"				
	Room 104					
DR-41	Ceiling	Texture	White Paint	5	ND	100% NF
			Grey, Cementicious	95	YES	7% Chrysotile, 93% NF

**R. S. MANAGEMENT
SERVICES INC.**

Asbestos Consulting & Project Management

CERTIFICATE OF ANALYSIS

Spreadsheet

Project 25-06 - City of N.B. - Lead Paint Samples
Attn; Mike Lepp

Building Name: Don Ross Center
891 - 99th Street
North Battleford, SK

Paint Samples from various surfaces

Date Sampled: June 18, 2025

[illegible]